

IPitomy IP550 SIP IP Telephone Handset Cradle Cushion

Proper placement of the IP550 Rubber Handset Cushion will address the issue of the IP550 handset slipping off the hook switch when the handset is positioned to the extreme bottom of the handset cradle. It is possible for the phone to be in an off hook state if it is lifted slightly from the cradle and pushed to the bottom of the handset cradle and not properly seated.

Place the rubber Handset Cradle Cushion as indicated in the photo below:

